

## FEATURES & BENEFITS

- OEM Experience and knowledge of applying this modification
- Most experienced facilities incorporating this highly technical Service Bulletin
- Three facilities capable of installing the Service Bulletin
- Service Bulletin requires “Highly Trained” and experienced personnel
- Can be accomplished during maintenance, winglets or prior to paint
- No Charge - Commercial Program is applicable to specific aircraft (by delivery date)



## DASSAULT FALCON JET DRY BAY CAPABILITIES

Following the rare occurrences of high speed runway excursions, analysis of the subsequent wing damage has identified that a potential fuel spill can occur on the aircraft. To prevent such a fuel spill, Dassault Falcon Jet has issued a Service Bulletin (S/B) to modify the wing design. The modification consists of adding a sealed boundary from fuel to a small part of the wing in the area of the wheel well, between ribs No. 4 and 5 in front of the rear spar. This results in an increased dry bay area. As a consequence of this situation, the European Aviation Safety Agency (EASA) has released the enclosed Airworthiness Directive (AD) No. 2011-0193, which mandates compliance with the AD before **April 19, 2024**. – Please review the Service Bulletin and AD applicable to your aircraft for up-to-date information.

## SCHEDULE

### Estimated Lead Time:

15 days

### Estimated Downtime/Schedule:

15 - 20 days

## INSTALLATION LOCATION

- Little Rock, AR
- Melbourne, FL
- Reno, NV

## AIRCRAFT

Falcon 900EX EASy (S/B 329)

Falcon 900DX (S/B 329)

Falcon 900LX (S/B 329)

Falcon 900EX (S/B 329)

Falcon 900C (S/B 388)

Falcon 900B (S/B 388)

Falcon 900A (S/B 388)

Falcon 2000 (S/B 388)

Falcon 2000EX (S/B 171)


Falcon 2000EX EASy (S/B 171)

Falcon 2000DX (S/B 171)

Falcon 50 (S/B 496)

Falcon 50EX (S/B 496)

## DASSAULT FALCON JET SERVICE CENTER LOCATIONS



- Little Rock, AR
- Melbourne, FL
- Reno, NV
- St. Louis, MO
- São Paulo Catarina, BRAZIL

MOBILE REPAIR UNITS (GoTeam only)

- Denver, CO area
- Stuart, FL area
- Teterboro, NJ area
- Van Nuys, CA area



Precision Structural Location



Door Installation and Sealant Coating



Successfull Dry Bay

For further details, please contact your DFJ service center Regional Sales Manager or e-mail [DFJServiceCenters@dassaultfalconjet.com](mailto:DFJServiceCenters@dassaultfalconjet.com).